

RTO Media Cleaning

Keeping your Regenerative Thermal Oxidizer (RTO) clean of unwanted residue can improve efficiency.

Regenerative Thermal Oxidizers (RTO) are used to destroy harmful emissions produced by certain manufacturing plants. RTOs heat volatile organic compounds (VOC) present in exhaust streams to high temperatures, leading to combustion. This process is called thermal oxidation.

While many volatile compounds are safely destroyed using this method, a benign residue can build up in the combustion chamber and media bed during operation. Residue entering the unit alongside exhaust streams can become stuck to the interior walls of the equipment and affect the machine's efficiency.

In some cases, the formulation of unwanted residue is the result of the combustion process itself and cannot be avoided. Regardless of the cause, RTO components must be properly maintained and media cleaned to keep the unit running smoothly.

What improvements will you see from cleaning your media?

- Improved destruction efficiency
- Restored thermal efficiency and airflow capacity
- Reduction in the increased fuel usage caused by plugging
- Increased equipment life by reducing stress on system components

RTO Media Cleaning Methods

The efficiency of the unit is crucial in meeting EPA regulations and manufacturing objectives. Built-up residue can decrease airflow and lead to higher fuel requirements. In addition, valve seals and other intricate components can become damaged by excessive layers of unwanted particulates. Therefore, maintenance of the equipment must be done on a regular basis.

There are two methods commonly used for cleaning an RTO system: bake-out and wash-down. The specific RTO and the type of media installed in the unit and the type of particulate (organic or inorganic) may affect which method you use. If you notice unusual drops or increases in pressure, fan speed, and fuel consumption, the unit may be in need of a bake-out or wash-down. Visit **www.thecmmgroup.com** to read about our solutions for VOC control, custom process equipment, and aftermarket services

Oxidizers/ Air Pollution Control Systems

- **Custom Process Equipment:**
- Ovens & Dryers
- Cheese Melters
- Coaters & Web Handling
- Energy Management Systems
 Ancillary Systems

Aftermarket:

- Rebuilds/Upgrades
- Preventive Maintenance
- Spare & Replacement Parts
- Services:
- Consulting Services
- Site Engineering
- Product Engineering
- Inspection ServicesTurnkey Installation

2071-C Lawrence Drive P.O. Box 5903 De Pere, WI 54115 ↓ +1 (920) 336-9800
 ↓ +1 (920) 336-9797
 ∞ info@thecmmgroup.com

thecmmgroup.com

The CMM Group can provide system and component upgrades, rebuilds, and retrofits, spare parts, catalyst cleaning, ceramic media and media replacement, and other aftermarket services.

Bake-Out Method

The bake-out method works in a similar manner as a self-cleaning oven. The media bed is heated to roughly 850 degrees Fahrenheit, causing any residue caught in the media to be incinerated. Each section of the unit is heated in succession to ensure all areas of the machine are thoroughly cleaned. Typically, the most affected areas in an RTO are the lower media bed and cold-face sections.

Once the bake-out has been completed, the unit can be reconnected and operated as normal. In some cases, the operation can be performed during production. Bake-outs are typically carried out manually; however, the unit can be programmed to automatically conduct a cleaning on a regular basis.

Wash-Down Method

The wash-down method uses water or solvent streams at low pressures to remove residue directly from the media bed. Due to the fact that this method is more hands-on and requires drying time, the entire process is typically longer than that of a bake-out. Taking pollution control units offline for regular cleans can halt production and impact overall manufacturing costs. However, cleaning residue from the interior chambers can increase the health and longevity of the unit, leading to increased productivity.

The costs of a regular media cleaning program are significantly lower than that of a full media bed replacement. The CMM Group has both the process knowledge and the field experience to assist you in selecting the best choice for your operation. However, should your media need to be replaced due to fouling, cold face condensation, or thermal stress, we can review the type of media being used, and determine its suitability for application. Contact us to discuss your RTO maintenance!

L +1 (920) 336-9800

+1 (920) 336-9797

➡ info@thecmmgroup.com

2071-C Lawrence Drive P.O. Box 5903 De Pere, WI 54115

thecmmgroup.com

For Service and Parts,

Call +1 (920) 336-9800

For more information on Preventative

Maintenance Programs, contact us at:

+1 (920) 336-9800

info@thecmmgroup.com

M-RMC21-2